

# Oil Field Environmental Incident Summary

**Incident:** 20140721091102 **Date/Time of Notice:** 07/21/2014 09:11

**Responsible Party:** HESS BAKKEN INVESTMENTS II, LLC

**Well Operator:** HESS BAKKEN INVESTMENTS II, LLC

**Well Name:** SC-BARNEY 154-98-1819H-3

**Field Name:** TRUAX

**Well File #:** 25284

**Date Incident:** 7/17/2014

**Time Incident:** 00:30

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 154

**Rng:** 98

**Sec:** 7

**Qtr:**

**Location Description:**

**Submitted By:** Jason Henry

**Received By:**

**Contact Person:** Jason Henry  
3015 16th Street SW, Suite 20  
Minot, ND 58701

**General Land Use:** Well/Facility Site

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 0.3 Mile

**Distance Nearest Water Well:** 0.3 Mile

**Type of Incident:** Fire

**Release Contained in Dike:** No

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0.5	Barrels			0	barrels

Brine

Other

**Description of Other Released Contaminant:**

**Inspected:** **Written Report Received:** 11/27/2015 **Clean Up Concluded:** 7/22/2014

## Risk Evaluation:

N/A - The fire near the flare burned itself out, and the well was shut down until the cause of fluid carryover to the flare could be determined.

## Areal Extent:

Approximately 20 feet by 30 feet.

**Potential Environmental Impacts:**

There were no potential receptors observed in the immediate vicinity of the release location.

**Action Taken or Planned:**

The fire near the flare stack burned itself out, and the well was shut down until the cause of the fluid carryover to the flare could be determined. The impacted soil will be excavated, stockpiled, and transported off-site to a properly permitted disposal facility.

**Wastes Disposal Location:** At a properly permitted disposal facility.

**Agencies Involved:**

**Updates**

---

**Date:** 7/21/2014    **Status:** Reviewed - Follow-up Required

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Fire on location. According to the report, a release of fluid during the fire appears to have sprayed off location. Followup is necessary.

---

**Date:** 9/8/2015    **Status:** Reviewed - Assigned to Other Agency

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on location 13:34 9/2/2015.

Extent of released materials appears to have remained on location.

NDIC retains oversight.